

Penn E&R's Discussion on Quarry No. 4

January 25, 2001

ORIGINAL



SDMS DocID 2050281

I) QUARRY NO. 4

- History and Location
- Investigation of Soil Conditions in Quarry No. 4
 - Three Previous Investigations
 - Twenty-Two Soil Samples Submitted for Analysis
 - Soil Sample Results:
 - VOCs
 - SVOCs
 - Pesticides/PCBs
 - Metals
 - Cyanide
 - TCLP Test Results
- Groundwater Quality in the Vicinity of Quarry No. 4
 - Location of Pertinent Wells
 - Groundwater Flow Direction
 - Groundwater Sample Results:
 - VOCs
 - SVOCs
 - Metals
 - Cyanide

II) 2201/2301 RENAISSANCE PROPERTIES

- Layout of the 2201 and 2301 Properties
 - Construction Activities Completed on 2201
 - Construction Activities Underway on 2301
- Location of Quarry No. 4 in Relationship to 2201/2301
- Capping Activities Completed/Underway on Quarry No. 4